## NASA TECHNICAL MEMORANDUM

## NASA TM X-73926

(NASA-TM-X-73920) CONCOPPE NOISE-INDUCED BILLDING 1-35A110NS, SULLY PLANTATION -F PORT NO. 2, CHANTILLY, VISGINIA (NASA) 46 P HC \$8.00 CSCL 13M

N76-30603

Unclas G3/39 48741

CONCORDE NOISE-INDUCED BUILDING VIBRATIONS
SULLY PLANTATION - REPORT NO. 2
CHANTILLY, VIRGINIA

Ву

Staff-Langley Research Center

June 1976

This informal documentation medium is used to provide accelerated or special release of technical information to selected users. The contents may not meet NASA formal editing and publication standards, may be revised, or may be incorporated in another publication.

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION LANGLEY RESEARCH CENTER, HAMPTON, VIRGINIA 23665



1. Report No.	2. Government Access	sion No	3. Recipient's Catalog	g No.				
NASA TM X-73926  4. Title and Subtitle	L		6 0					
Concorde Noise-Induced Build	ling Vibration	s. Sully	5. Report Date June 1976					
Plantation - Report No. 2, (			6. Performing Organi 2630	zation Code				
7. Author(s)			8. Performing Organiz	ration Report No.				
Staff-Langley Research Cente	er*							
9. Performing Organization Name and Address			10. Work Unit No.					
NASA-Langley Research Center	•	Ļ	505-09-13-0					
Hampton, VA 23665			11. Contract or Grant	No				
			13. Type of Report at	nd Period Covered				
12. Sponsoring Agency Name and Address			Technical Mem	norandum				
National Aeronautics and Spa Washington, DC 20546	ice Administra	tion	14. Sponsoring Agency					
15. Supplementary Notes *Acoustics and Noise Reduct W. H. Mayes, H. F. Scholl, D. G. Stephens, B. G. Holl		R. DeLoa	ent Research [ ch, H. K. Hol wis, J. W. Ly	lmes,				
noise-induced building vibra approach is to record the le outdoor noise levels in sele International Airport. Pres Plantation, Chantilly, Virgi and June 14 through June 17, the vibration levels of wind Concorde operations, other a in this report are drawn from larger than the May data bas levels of window, wall and foperations are higher than the aircraft. Furthermore, the higher than those of the wall aircraft than recorded nonaits ship with the overall sound Concorde may cause more vibrations of the noise.	tions associal vels of inducted homes, hented herein nia during the 1976. Record lows, walls, for the combined e covered in loor vibratory vibratory results and floors recraft events pressure leveration than a contract than a contract expenses	ted with Concorded vibrations an istoric and othe are representative periods of Mayded data provide lours, and the nonaircraft evend May-June data the first reporty response resultevels associate ponses of the with the window reand exhibits at the conventional airs associated with the conventional airs associated with the conventional airs associated with the vibrations and exhibits at the conventional airs associated with the conventional airs associated with the conventions and exhibits at the conventional airs associated with the conventions and the conventions are conventions and the conventions are conventions and the conventions are conventions as a conventions are conventions as a conventions and the conventions are conventions as a conventions are conventions and the conventions are conventions and the conventions are conventions	e operations. d associated r buildings now data recorporate associated to the resurbase which is NASA TM X-7 ting from Condows are consponse is high linear responsound pressurcaft due to h Concorde ap	The indoor/ lear Dulles ded at Sully lay 28, 1976, is between led with led some considerably 3919. The corde led led siderably her for se relatione level, the spectral or pear to be				
17. Key Words (Suggested by Author(s)) (STAF	category underlined)	18. Distribution Statement		<del></del>				
Noise, building vibrations, structural response to noise								
, in the second	71 Unlimited							
19 Security Classif. (of this report) Unclassified								

# CONCORDE NOISE-INDUCED BUILDING VIBRATIONS SULLY PLANTATION - REPORT NO. 2 CHANTILLY, VIRGINIA

By Staff-Langley Research Center\*

#### SUMMARY

This is the second report on a series of planned studies to assess the noise-induced building vibrations associated with Concorde operations. The approach is to record the levels of induced vibrations and associated indoor/ outdoor noise levels in selected homes, historic and other buildings near Dulles International Airport. Presented herein are representative data recorded at Sully Plantation, Chantilly, Virginia during the periods of May 20 through May 28, 1976, and June 14 through June 17, 1976. Recorded data provide relationships between the vibration levels of windows, walls, floors, and the noise associated with Concorde operations, other aircraft, and nonaircraft events. The results presented in this report are drawn from the combined May-June data base which is considerably larger than the May data base covered in the first report, NASA TM X-73919. The levels of window, wall and floor vibratory response resulting from Concorde operations are higher than the vibratory levels associated with conventional aircraft. Furthermore, the vibratory responses of the windows are considerably higher than those of the walls and floors. The window response is higher for aircraft than recorded nonaircraft events and exhibits a linear response relationship with the overall sound pressure level. For a given sound pressure level, the Concorde may cause more vibration than a conventional aircraft due to spectral or other differences. However, the responses associated with Concorde appear to be much more dependent upon sound pressure level than spectral or other characteristics of the noise.

<sup>\*</sup>Acoustics and Noise Reduction Division

W. H. Mayes, H. F. Scholl,

D. G. Stephens, B. G. Holliday

R. B. Lewis, J. W. Lynch

#### INTRODUCTION

The vibratory response of historic and other buildings resulting from Concorde operations and the associated effects in terms of structural damage and human annoyance have been the subject of public concern (ref. 1). As a result of this concern, measurements of Concorde noise-induced building vibrations (ref. 2) are being conducted as part of the total Concorde assessment program. The first study in this phase of the assessment was carried out at Sully Plantation during the time period of May 20 through May 28, 1976, and reported in NASA TM X-73919 and (ref. 3). A second study was conducted at Sully Plantation from June 14 to June 17, 1976, to expand the data base. The results from the combined May-June data base are presented herein.

The approach to the assessment of Concorde noise-induced building vibrations involves the following steps: (1) the measurement of the vibratory response of windows, walls, and floors for selected historic (e.g., Sully Plantation), and other buildings; (2) the development of functional relationships ("signatures") between the vibration response of building elements and the range of outdoor and/or indoor noise levels associated with events of interest; (3) a comparison of the Concorde induced response with the response associated with other aircraft as well as common domestic events and/or criteria. The development of vibration/noise relationships or signatures (step 2) allows one to determine the response of the structure under study or a similar structure to any (similar) noise level of interest. This procedure reduces the reliance on maximum response levels and the associated statistical difficulty resulting from small sample sizes. Also the precise location of the noise source is not essential to this approach.

This report, which is the second in a series of reports, includes a brief overview of the tests conducted at Sully Plantation including data acquisition and reduction schemes, a log of the recorded events, and results. Results are presented in terms of the levels of vibration and noise associated with Concorde, other aircraft and nonaircraft events, the vibration-noise relationships or signatures (for the window) associated with the aircraft, and comparisons of Concorde induced response with other aircraft and nonaircraft events.

#### TEST SITE DESCRIPTION

#### Location

Figure 1 shows the location of Sully Plantation adjacent to Sully Road (Virginia State Route 28) 1.2 kilometers north of U.S. Route 50 in Chantilly, Virginia. The Plantation is 6.4 kilometers south of the Dulles Airport access road and approximately 2.2 kilometers south-southeast from the end of Dulles Airport Runway 19L.

#### Structural Details

Figure 2 is a photograph of the east elevation of Sully Plantation showing an Air France Concorde departing from runway 19L. As described in reference 4, the building is a two and one-half story central section flanked by asymmetrical one and one-half story gabled wings. Its foundation of red sandstone, averaging almost 60 cm in thickness, support walls which are sheathed by clapboards that cover a heavy mortise-and-tenon framing. The walls of the earliest portion of the house are insulated by means of the common 18th century "nogging" (filled with brick). Photographs showing structural details of the wall are presented in reference 3. Random width pine flooring attached directly to floor joists

is used throughout the house (no subfloor). Windows are generally the 12 over 12 sashing type with some being 9 over 9, 6 over 9, and 6 over 6. Of the 324 window panes at Sully, half are original and a typical pane measures 20.3 cm by 25.4 cm and varies from 0.16 cm to 0.32 cm in thickness. All of the panes have been covered with transparent plastic Scotch-tint film to aid in reflecting sunlight.

The first floor of Sully contains three major rooms in addition to the main entrance hallway. The upstairs has two spacious bedrooms, a large chamber, and a small lodging room.

Figure 3 shows a plan view of the first floor of Sully Plantation including test instrumentation locations. In the May test, the instrumentation systems were located in the parlor and south drawing room; in the June test only the north parlor was instrumented. The instrument systems consisted of three accelerometers and one microphone for each room. Installation of the instruments is shown in figures 4 through 6. Microphones were located outside of the building as shown in the figure.

#### DATA LOG

Data at the Sully Plantation test site were recorded during the period May 20 through May 28, 1976, and June 14 through June 17, 1976. Table I is a chronological listing of events during the May time period and Table II is a listing for the June tests. A total of 169 events were measured which included not only aircraft operations and room calibrations but typical house occurrences such as visiting tour groups, a vacuum cleaner, chair falling, etc. A summary of recorded events for both test periods is presented in Table III.

#### DATA ACQUISITION AND PROCEDURE

#### Instrumentation

The details of the instrumentation system deployed during the May tests are described in reference 3. The second series of measurements at Sully Plantation, June 1976, was conducted using a mobile laboratory containing both an analog acquisition system and an on-line digital processing system. Data were obtained only from the parlor or north room during the June test and consisted of acoustic measurements of interior and exterior sound pressure levels as well as vibration levels of the floor, exterior wall, and window. Conventional Bruel and Kjaer equipment was used for the sound measurements and piezoelectric crystal accelerometers, employing in-house developed signal conditioning, were used for the vibration measurements. All data were recorded on analog FM tape for further analysis. On-line analog x-y plots of window vibration response versus outside sound pressure level were obtained for many of the events. The primary system used for on-line acquisition consisted of a General Radio 1926 true Pms log voltmeter which provided overall or magnitude values each one-half second for the five information channels. A Hewlett-Packard 2!M20 digital computer was then used to assemble these data into tabulations of the time history values for line printing and for "Calcomp" plots of the acoustic time histories as well as plots of selected acceleration levels as a function of outside sound pressure levels. Figure 7 is a block diagram of the instrument system used in this test.

#### Frequency Response and Calibration Procedures

In addition to extensive pretest documentation of frequency response, deviation linearities, gain accuracies and dynamic range, daily calibrations consisted of: tape recorder sensitivity (deviation) checks, pink noise (voltage) insertion in the microphone channels, one-half volt sine wave reference voltage insertion into accelerometer channels, and 250 Hz piston-phone acoustic calibration of the microphone systems for pretest and posttest as a minimum and more frequently, time permitting. Frequency response of the acoustic channels is nominally  $\pm$  1 dB over the range from approximately 5 Hz to 10 kHz and  $\pm$  1/2 dB over the range from approximately 3 Hz to in excess of 3 kHz for the accelerometer channels.

#### Test Procedures and Communications

Visual observation of airport activity via an opening in the roof of the house, monitoring tower communications with aircraft in the area, and/or spotters located some distance from the plantation were used to identify aircraft operations as well as to control and coordinate data acquisition. Time code was recorded to provide a common time for use in later analysis. Because the computer required 5 to 10 minutes to completely analyze each flyover, those events which were not obtained in real time with the computer were readily obtained from tape playback.

#### Reference Acoustic Source

To provide a controlled acoustic input into each of the rooms, an Altec Model 9844A, playback/monitor speaker system having a frequency response extending from approximately 50 Hz to 15 kHz was used as the transducer. The speaker system contains two 12 inch (30.48 cm) speakers and a high-frequency horn. USASI shaped noise spectra at several acoustic levels (as monitored on a hand-held sound level meter) were impressed on the wall from approximately 6 feet (1.83 meters) away and data recordings made. Some sine wave testing was also performed. Figure 8 shows this system in the parlor (north room) essentially as it was positioned for the calibration tests.

#### PRESENTATION OF RESULTS

The data obtained during the May test period indicated that the maximum vibratory response resulting from aircraft operations occurred in the north room (parlor) which faces the Dulles runways and was associated with aircraft takeoff operations. Furthermore, the maximum aircraft-induced vibrations were associated with Concorde operations, however, there were too few Concorde operations to compare (with confidence) Concorde with other aircraft. Thus, a second series of tests was conducted during June 1976 to extend the data base. Data were recorded in the north room only during the June series and were limited to takeoff operations.

#### Levels of Vibration

The maximum levels of vibration recorded on the windows, walls and floor for the various events are shown in Tables IV and V and figures 9 through 11 along with the associated overall sound pressure levels. In general, each bar

contains the maximum values recorded for several events. The Concorde induced response is seen to exceed the response due to other aircraft and nonaircraft events for the window. The wall and floor, however, exhibit comparable or greater response for nonaircraft events. The responses of the floor and wall are considerably lower than the window response which may be due to the atypical construction such as "nogging" and large floor joists.

#### Signatures

In order to quantitatively assess the relationships between aircraft noise levels and the corresponding levels of vibration induced in the window, response signatures (plots of window acceleration versus sound pressure level) were made for each flyover event. A least squares regression analysis was performed for each signature to calculate the slope and ordinate intercept for the best straight line fitting the response signature data. A correlation coefficient was also calculated for each signature to determine how well the best straight line fit the data. The correlation coefficient can range from zero (no correlation) to one (perfect correlation). Response signatures for which the correlation coefficient exceeded an arbitrarily selected threshold of 0.6 were retained for further quantitative analysis. Data for several events were then grouped by aircraft type and the composite response signatures displayed in figures 12 through 16 were generated. Listed by aircraft type in Table VI are the slopes, ordinate intercepts, and correlation coefficients for each of the events used to compile the composite response signatures in figures 12 through 16. Also listed in Table VI are the straight line parameters for these composite signatures. A composite response signature based on all non-Concorde flights was also generated (figure 17) for comparison with the Concorde signature (figure 12).

#### Comparative Response

It has been suggested that, for a given sound pressure level, vibration induced in structures by Concorde may be different than vibration levels (ref. 5) induced by conventional jet transports. To investigate this question, curves were generated in which, for a given sound pressure level, Concorde induced vibration levels were divided by the vibration levels caused by convention 1 aircraft. (The vibration levels were determined from the regression curves in figures 12 through 17.) These "response ratios" were then plotted (figure 18) as a function of sound pressure level. In figure 18a, response ratios for a number of individual aircraft are presented. Figure 18b represents the composite response ratio curve for all conventional aircraft compared to Concorde, based on the regression curves of figures 12 and 17. These response ratios suggest that for sound levels of about 90 to 100 dB and below (the range of most conventional aircraft operations near Sully), the Concorde generally induced lower vibration levels in the north parlor window than did conventional jet transports. At higher sound levels, the Concorde is apparently more efficient in exciting a window response; however, this last conclusion is necessarily based on an extrapolation of conventional jet noise to higher levels and must therefore be construed as tentative. The DC-8 represents one exception to the general trend; it consistently generated higher vibration levels in the window than the Concorde for a given sound level. It should be noted that, because of the higher sound levels associated with Concorde operations, maximum absolute vibration levels induced in the window by Concorde are generally higher than the peak vibration levels induced by conventional aircraft.

#### CONCLUDING REMARKS

The 'allowing conclusions are based on building vibratory response measurements at Sully Plantation for 128 aircraft flyovers (7 Concorde) and 21 household or other activities including door slams, radio, vacuum cleaner, traffic noise, etc. Maximum response to aircraft was recorded in a north room facing the runways and was associated with takeoff operations. The following comments apply to the north room during the May-June 1976 test series:

- 1. The Concorde noise-induced vibration levels of the windows, walls and floors are higher by a factor of 2 or more than the levels resulting from conventional aircraft operations.
- 2. The window response levels associated with aircraft operations (0.432  $g_{rms}$  maximum) are higher by a factor of 2 or more than the wall and floor response possibly due to the atypical heavy construction of the walls and floors at Sully.
- 3. The window response is higher for aircraft than nonaircraft events, the wall response to aircraft and nonaircraft are comparable, and the nonaircraft events result in higher floor response.
- 4. At a given sound pressure level, the window generally responds somewhat differently to different aircraft, however, these aircraft-to-aircraft variations are small compared to the range of vibration levels encountered for a given flyover. This result suggests that the absolute vibration levels induced in the window during a flyover depend more on the overall sound pressure level associated with that flyover than on any other characteristics of the source.
- 5. At a given sound pressure level, the Concorde may cause slightly more window vibration response than conventional aircraft when the noise levels are

high and lower relative response when the noise levels are low. The response ratio calculated from measured data (Concorde g/aircraft g) ranged from a maximum of 2 at high noise levels to about 0.5 at low levels.

6. The window response exhibits a linear relationship with overall sound pressure level. The responses of the walls and floor are not of sufficient range to develop a noise-vibration relationship. This latter fact suggests that more typical building structures be examined to determine such relationships.

#### REFERENCES

- 1. Concorde Supersonic Transport Aircraft Final Environmental Impact Statement, Volume 1. U.S. Department of Transportation, Federal Aviation Administration, September 1975.
- 2. Structures Directorate-NASA Langley Research Center: The Assessment of Concorde Noise-Induced Building Vibrations A Study Plan, Mar. 8, 1976.
- 3. Concorde Monituring Monthly Report, Gulles International Airport: U.S. Department of Transportation. Federal Aviation Administration, May 1976.
- 4. Gamble, Robert S.: Sully The Biography of a House. Sully Foundation Limited, Chantilly, Virginia, 1973.
- 5. Department of Evansportation, United States of America: The Secretary's Decision on Concorde Supersonic Transport. Washington, DC, Feb. 4, 1976.

TABLE I.- OPERATIONS LOG MAY 1976

																	:				
	REMARKS		USASI Noise	USASI Noise	USASI Noise		USASI Noise	USASI Noise				!									
RATION	PARLOR	1								•	•	ı	•	1	ı					•	1
BUILDING OPERATION	DRAWING ROOM	•	90 dB Cal.	80 dB Cal.	70 dB Cal.	Ambient Cal.	90 dB Cal.	80 dB Cal.	Ambient Cal.	ı			ſ	1	•	1				1	1
AIRCRAFT	OPERATION	Landing			ı	1		ı		Landing	Landing	Takeoff	Takeoff	Takeoff	Overhead	Takeoff	Takeoff	Landing	Landing	Landing	Landing
AIRCRAFT	TYPE	DC-8			1	1		1		DC-8	727	727	707	DC-8	Helicopter	727	DC-9	DC-9	Gen. Av. Jet	727	R-5 Navy
	RUNWAY	IR	1	•	1	•	ı	1	•	IR	IR	191	19L	191	ı	19L	16T	IR	IR	IR	IR
Ą	P.M.	4:55														12:06	1:08	3:13	•		
TIME	A.M.		8:45	8:50	8:55	00:6	05:6	01:01	10:20	11:00	11:34	11:36	11:37	11:44	11:52				•	10:23	10:25
	DATE	5-20-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-21-76	5-22-76	5-22-76	5-22-76
EVENT	NO	101	102	103	10,	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120

TABLE I (Cont'd).- OPERATIONS LOG MAY 1976

					T		Γ	Γ	Γ				<u> </u>				<del>                                     </del>				
	REMARKS																				
	RATION PARLOR	1	1	,				1	ı	-	1	I	•	1	1	,	1	1	1	ł	1
THE CHILD	DRAWING ROOM PARL	•	•	ı			J		ı		1	t	1	ı		1	1	•	1	•	1
TOACOUTA	OPERATION	Landing	Landing	Landing	Landing	Touch and Go	Touch and Go	Landing	Touch and Go	Landing											
ATOODAGT	TYPE	707	727	DC-8	DC-9	727	747	747	747	727	707	727	Concorde	Concorde	707	727	707	707	727	707	727
	RUMMAY	18	IR	IR	IR	IR	IR	IR	IR	IR	IR										
Ę	P.M.					12:20											-				
6	A.M.	10:50	10:58	11:10	11:50		9:12	9:25	65:6	10:50	10:56	11:10	11:50	11:53	9:04	91:6	I	10:16	10:19	10:38	10:50
	DATE	5-22-76	5-22-76	5-22-76	5-22-76	5-22-76	5-24-76	5-24-76	5-24-76	5-24-76	5-24-76	5-24-76	5-24-76	5-24-76	5-25-76	5-25-76	5-25-76	5-25-76	5-25-76	5-25-76	5-25-76
tal carro	No.	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140

TABLE I (Cont'd).- OPERATIONS LOG MAY 1976

	1																		-		
DEWADVC	NEWANNS																Adults	Adults	Adults		
ERATION	PARLOR	,	,	+	,	1	•	_	1	•	1	-	•	1		•			Tour Group 4-6 People	Door Slams	Door Slams
BUILDING OPERATION	DRAWING ROOM		ı	•	1	•		1	,	1	•	•	-	-	•	•	Tour Group 20-30 People	Tour Group 20-30 People		ı	ı
AIRCPAFT	OPERATION	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff		•	1	1	1
AIRCRAFT	TYPE	Concorde	Concorde	727	BAC-111	BAC-111	BAC-111	727	707	DC-8	707	727	727	747	BAC-111 or DC-9	727	1	-	8	•	•
RITMINAY	MOMMAI	19L	19R	19L	19L	16L	16T	<b>161</b>	16T	161	16T	16T	16T	19L	161	16T		1	#		
	P.M.	12:05	12:59	3:10	3:33	3:45	3:55										1:25	1:29	1:32	1:40	1:42
TI	A.M.							8:56	9:13	9:23	9:30	9:48	10:03	10:13	11:09	11:11					
በልጥድ	DALL	5-25-76	5-25-76	5-25-76	5-25-76	5-25-76	5-25-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76
EVENT	No.	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160

TABLE I (Cont'd).- OPERATIONS LOG MAY 1976

	_	_				······			,	_				<del></del>		<del></del>
	REMARKS							USASI Noise	USASI Noise	USASI Noise	USASI Noise	Sine Wave	Sine Wave	Sine Wave	Children	Children
RATION	PARLOR	•	1	1	Radio Playing	Ambient Cal.	Vacuum Cleaner	∂5 dB Cal.	90 dB Cal.	95 dB Cal.	100 dB Cal.	20-100 Hz Cal.	100-1 kHz Cal.	100-200 Hz Cal.	1	Tour Group 4-6 People
BUILDING OPERATION	DRAWING ROOM	Chair Falling	Chair Falling	Radio Playing		Ambient Cal.	•	1	•	1	-	•	•	1	Tour Group 20-30 People	I
AIRCRAFT	OPERATION	ı		ı	-	•	-		•	1		•	1	ı	•	
AIRCRAFT	TYPE	J		•	e .	•	•	_	•	•	•	_	•	•	•	
	RUNWAY		•	•	-			4	•	1			ı	1	•	_
É	P.M.	1:43	1:55	2:04	2:07	2:18	2:23									
TIME	A.M.							9:38	6:47	9:57	10:06	10:11	10:15	10:21	10:32	10:45
	DATE	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-26-76	5-27-76	5-27-76	5-27-76	5-27-76	5-27-76	5-27-76	5-27-76	5-27-76	5-27-76
EVENT	No.	191	162	163	164	165	166	167	168	169	170	171	172	173	174	175

TABLE I (Concluded). - OPERATIONS LOG MAY 1976

TABLE II.- OPERATIONS LOG JUNE 1976

	REMARKS		1	•	1	•	1	1	ŧ	•	ı	•	•		Television (generalistica) & mp. st.	1		ŧ	•	
SATION	PARLOR		1	-	1	•	•	1	1	1	•	ŧ	1	ı	•	ı	ı	1	1	
BUILDING OPERATION	DRAWING ROOM		t	1	1	•	l	ů.	\$	1		•	•	4	•	ŧ	•	4	1	
AIRCRAFT	OPERATION		Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takenff							
AIRCRAFT	TYPE		707	8-DG	202	727	727	747	202	707	727	727	727	DC-10	DC-8	727	707	Concorde	727	727
	RUNWAY		19L	19L	16I	161	751	161	161	<b>761</b>	761	<b>761</b>	761	761	161	16T	161	161	161	161
TIME	P.M.	void														-		1:01	3:14	3.47
T	A.M.		9:12	9:22	9:29	9:48	10:04	10:24	10:26	10:35	11:08	11:25	11:36	11:53	12:13	12:15	12:25			
	DATE		6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76
EVENT	NO.	194	195	196	197	198	199	200	201	202	203	204	205	206	202	208	509	210	211	212

TABLE II (Cont'd).- OPERATIONS LOG JUNE 1976

Г			1			1		-	]			1	1					]	]	•
	REMARKS						•	•						•	ı			The state of the s		
RATION	PARLOR		•	•	ŧ			1	•	'	ı		ı	ı	•	•	ı			
BUILDING OPERATION	DRAWING ROOM	ı	ı	ı	•	•	-	•	1	•	•	•	1	•	•	•	•		•	
AIRCRAFT	OPERATION	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff
AIRCRAFT	TYPE	747	8 <b>~</b> ⊃⊓	6DC	727	727	DC-9	707	202	707	L-1011	8-DC	DC-10	707	707	727	DC-10	707	737	DC-8
	RUNWAY	16I	161	16T	16I		19L	19L	16I	19L	16I	19L	19L	19L	19L	19L	16T	161	19L	19L
TIME	Р.М.	3:57	4:04	4:06	4:15	4:55	5:01	5:03	5:23	5:24	5:28	5:35	5:52	5:59	6:02	6:10	6:12	6:14	6:16	6:18
T	A.M.																			
	DATE	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76
EVENT	NO.	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231

TABLE II (Cont'd).- OPERATIONS LOG JUNE 1976

-	1		<b>-</b>	Γ.						_		-	]		]	1		•	-	1	1
	REMARKS	2	1	ı	•		•	•	1					•		1	•	1		•	•
RATION	PARLOP.	•	ı	•	ſ	•	•	•	ŧ			1	ı	•	1	8	•	•	•	•	•
BUILDING OPERATION	DRAWING ROOM	-	1	1	-	1		•			•	<b>t</b>	•	1	1		•	ı	1	•	
AIRCRAFT	OPERATION	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takjoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff
AIRCRAFT	TYPE	707	6-0Q	747	707	727	707	727	727	747	727	8-DQ	6-3G	DC-10	8-DC-8	747	DC-8	6-00	1-1011	DC-8	707
	JNWAY	19L	19L	19L	161	16T	16T	161	16T	16T	16T	761	16I	761	16T	16T	161	<b>161</b>	16I	19L	19L
1 1	P.M.	6:24	6:38	6:37	6:45	6:48	6:58	7:02	7:04			12:07	12:23	12:29	12:33	3:51	4:05	5:24	5:37	5:47	6:02
TIME	A.M.									10:14	11:32										
	DATE	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-14-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-67
EVENT	NO	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251

TABLE II (Cont'd).- OPERATIONS LOG JUNE 1976

1-	11	r	<b>)</b>	,	1 1			Ī	•		· 1		3	1 7	i .	1 1
	REMARKS	•		•	1	4	•		1	•		ı	1	ı		1
RATION	PARLOR	-	•	•	•	•	ı	•		1	•	1	l.	1	1	ı
B'ILDING OPERATION	DRAWING ROOM	•	1	1	•	•	•		•	1	1	•	8			ı
AIRCRAFT	OPERATION	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeoff	Takeofí	Takeoft	Takeoff	Takeoff
AIRCRAFT	TYPE	DC-10	DC-10	707	DC-8	General Aviation Jet	737	747	727	727	727	707	DC-10	DC-8	6-00	Concorde
	RUNWAY	16T	19L	19L	19L	19L	19L	19L	19L	19L	161	19L	19L	19L	16I	19L
ME	P.M.	9:05	6:14	6:16	6:20	6:26	6:29	6:39						12:11	12:26	1:01
TIME	A.M.								11:13	11:23	11:32	11:44	11:52			
	DATE	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-15-76	6-17-76	6-17-76	6-17-76	6-17-76	6-17-76	6-17-76	6-17-76	6-17-76
EVENT	NO.	252	253	254	255	256	257	258	259	260	261	262	263	264	265	566

TABLE II (Concluded).- OPERATIONS LOG JUNE 1976

	REMARKS	From 4 feet high	From 3 feet high	180 # person	180 # person
RATION	PARLOR	Dropped book on floor	Dropped book on floor	Stepped from chair onto floor	Stepped from chair onto floor
BUILDING OPERATION	DRAWING ROOM	-	1	1	t
AIRCRAFT	OPERATION	1	ı	-	•
AIRCRAFT	TYPE	ı	1	ı	ı
	RUNWAY	ı	•	•	•
TIME	P.M.	1:34	1:35	1:37	1:38
L	A.M.				
	DATE	6-17-76	6-17-76	6-17-76	6-17-76
EVENT	NO.	267 .	268	269	270

### TABLE III. - SUMMARY OF RECORDED EVENTS

## AIRCRAFT EVENTS

	May 20-2	28, 1976	June 14-1	7, 1976
	TAKEOFF	LANDING	TAKEOFF	LANDING
707 727	5 7	6 9	17 18	0
737 747	0	0 4		0
DC-8 DC-9	2	3 2	1 <u>1</u>	0
DC-10 BAC-111	0	0	7	0
L-1011 Helicopter	0	0	2	0
General Aviation Jet R-5 Navy Propeller	2	]	1	0
C-130 Propeller Concorde	) ] 3	0	0	0
TOTALS	28	28	72	0

## SPECIAL EVENTS

	May 20-28, 1976	June 14-17, 1976
Tour Groups	5	0
Door Slams	ĺ	0
Chair Step	0	2
Chair Drop	2	0
Book Drop	0	2
Radio Playing	2	0
Vacuum Cleaner On	1	0
Trucks Passing By	6	0
TOTALS	17	4

Calibrates - 20

Total Events - 169

TABLE IV.- MAXIMUM VALUES OF AIRCRAFT TAKEOFF
VIBRATION RESPONSE MEASUREMENTS

		Exterior	OA Acceleration, g <sub>rms</sub>		
Aircraft	Event	Overall SPL, dB*	Window	Wall ——	Floor
Concorde	141	106.1	.432	.048	.024
0011001 00	142	81.1	.019	.010	.008
	176	85.3	.039	.012	.014
	210	107.7	.335	.038	.166
	266	106.6	.351	.047	.077
DC-8	113	95.2	.090	.013	.017
	207	92.6	.105	.020	.046
	214	86.3	.055	.018	.021
	223	95.1	.182	.020	.018
	231	95.4	.209	.021	.025
	242	99.5	.229	.023	.016
	247	84.8	.052	.017	.016
	250	98.1	.138	.018	.020
	255	98.2	.155	.018	.018
	264	93.5	.091	.025	.030
B-707	112	95.0	.044	.014	.021
	149	100.2	.160	.028	.021
	195	88.0	.076	. J15	.019
	197	94.4	.106	.016	.031
	201	91.5	.078	.015	.024
	202	90.6	.082	.015	.027
	209	94.0	.130	.020	.046
	219	88.0	.045	.019	.018
	220	86.7	.064	.018	.015
	221	80.5	.032	.017	.018
	225	86.7	.075	.022	.019
	226	88.0	.079	.019	.019
	229	88.5	.063	.018	.017
	232	91.0	.052	.020	.017
	235	92.2	.108	.020	.022
	237	98.8	.145	.021	.024
	251	90.9	.064	.016	.014
<del></del>	254	103.4	.119	.020	.018
B-727	115	86.2	.120	.025	.023
	151	90.3	.078	.019	.017
	152	82.2	.041	.019	.018
	198	88.0	.064	.015	.022

<sup>\*</sup>SPL values correspond to max vibration level and do not necessarily represent max recorded SPL values.

TABLE IV (Concluded).- MAXIMUM VALUES OF AIRCRAFT TAKEOFF
VIBRATION RESPONSE MEASUREMENTS

		Exterior	OA Acceleration, g <sub>rm</sub>		
Aircraft	Event	Overall SPL, dB*	Window	Wall	Floor
B-727	203	87.3	.068	.016	.028
(Cont'd)	205	83.3	.060	.016	.016
(000 0)	211	86.4	.067	.019	.035
	212	95.1	.092	.021	.026
	216	88.0	.072	.022	.026
	217	87.3	.076	.018	.034
	227	88.8	.093	.025	.019
	236	89.0	.078	.019	.017
	238	88.0	.058	.016	.019
	239	90.9	.073	.019	.016
	241	94.8	.072	.018	.020
	259	87.9	.038	.022	.026
	260	90.1	.063	.023	.027
<u></u>	261	93.2	.062	.026	.030
L-1011	222	88.5	.064	.018	.016
	249	87.6	.046	.018	.016
DC-9	116	86.1	.037	.013	.013
	215	83.6	.046	.017	.017
	218	83.2	.035	.020	.018
	233	82.9	.057	.020	.017
	243	82.3	.035	.018	.018
	248	85.0	.036	.016	.015
DC-10	265	84.4	.045	016	.016
DC-10	206	83.4	.037	.016	.017
	224	84.4	.046	.016	.016
	228	85.1	.044	.023	.019
	244 252	83.7 86.5	.034 .036	.018 .014	.018
	252 253	80.2_	.030	016	.014 .015
B-747	153	88.8	.051	.022	.020
0-141	192	92.0	.091	.013	.014
	200	87.1	. 052	.016	.017
	213	85.7	.046	.019	.018
	234	86.5	.054	.017	.017
	240	92.6	.089	.020	.019
	246	85.9	.054	.016	.016
	258	83.8	.043	.013	.013

<sup>\*</sup>SPL values correspond to max vibration level and do not necessarily represent max recorded SPL values.

TABLE V.- MAXIMUM VALUES OF VIBRATION RESPONSE DATA DUE TO SPECIAL EVENTS

		OA SPL	., dB*	OA Acc	eleration,	9rms
Activity	<u>Event</u>	Ext.	Int.	Window	Wall	Floor
Tour Group	175	NA	73.3	.013	.013	.068
Vacuum Cleaner	166	NA	96.3	.105	.025	.065
USASI Noise	167	NA	85.0	.025	.015	.018
USASI Noise	168	NA	91.0	.042	.016	.023
USASI Noise	169	NA	96.0	.084	.020	.036
USASI Noise	170	NA	102.0	.143	.029	.064
Book Drop**	268	NA	NA	****	.18	3.8
Step From Chair to Floor**	269	NA	NA		<.04	1.0
Traffic	186	70.8		.013	.013	.013

<sup>\*</sup>SPL values correspond to max vibration level and do not necessarily represent max recorded SPL values.
\*\*Peak acceleration level, g's.

TABLE VL - RESPONSE SIGNATURE PARAMETERS

A. Concorde				
Event	Slope	Y-Int.	Coef.	No. Pts.
266	.851	18.36	.974	19
141	1.31	-27.3	.965	30
142	.594	35.36	.384	19
176	.658	34.06	.607	25
210	.969	4.601	.862	22
Composite	.971	5.454	.915	115
B. <u>DC-8</u>				
207 214	.963 .971	<b>8.582</b> 8.059	. 806 . 684	38 30
223	1.12	-4.18	.804	30
264	1.00	4.372	.831	33
231	1.11	-4.18	.863	39
242	1.03	.8813	.937	33
25°1	1.00	3.676	.777	37
1.	1.12	-5.07	.954	29
149 255	.851 1.25	17.48 -18.4	.918 .915	40 30
Composite	. 982	6.634	.841	339
C. <u>707</u>				
195	.802	23.6?	.624	23
197	.774	25.68	.766	27
201 202	.813 .889	22.15 15.33	.725 .757	18 27
202 209	.910	12.64	.737 .707	27
219	.720	29.15	.703	24
225	.986	8.522	.616	13
226	. 740	27.88	.794	31
229	.911	15.05	.647	20
235	.963	9.353	.827	19
237	.939	11.21	.864	24
251 112	.817 1.09	21.46 -5.36	.717 .885	20 24
150	.899	14.32	.892	15
190	.939	9.776	.929	22
254	.764	24.50	.950	22
Composite	.778	24.78	.768	356
D. <u>727</u>				
205	.701	31.68	.666	19
211	.917	14.04	.638	17
212	.596	40.58	.710	27
236	1.09	-1.14	.865	17
241	.428	54.44	.695	21
260	.586	41.42	.823 .846	17 19
261 151	. 522 . 796	47.29 23.66	.678	25
Composite	.596	40.49	.685	162
E. <u>747</u>				
213	1.17	-7.90	.969	5
192	.726	27 11	.766	23
240	.732	21	.800	31
245	.878	16.24	.650	26
200	1.04	2.088	.774	•
Composite	.677	32.25		2/
F. CTOL				
Composite	.821	21.01		954




Figure 1.- Location of Sully Plantation




Figure 2.- East elevation of Sully Plantation showing Concorde takeoff from 19L




Figure 3.- First floor plan view showing transducer locations.



Figure 4.- Location of accelerometer for wall vibration measurements.

Figure 5.- Location of accelerometer for window vibration measurements.

ORIGINAL PAGE IS OF POOR QUALITY




Figure 6.- Location of accelerometer for floor vibration measurements.

ORIGINAL PAGE IS OF POOR QUALITY




Figure 7.- Block diagrams of mobile data acquisition and processing system.

Figure 8.- Acoustic calibration.

ORIGINAL PAGE IS
OF POOR QUALITY




Figure 9.- Maximum levels of recorded vibration and noise for north window.




Figure 10.- Maximum levels of recorded vibration and noise for wall.




Figure 11.- Maximum levels of recorded vibration and noise for floor.

## RESPONSE SIGNATURE FOR CONCORDE




Figure 12.- North window vibration response for Concorde takeoff.




Figure 13.- North window vibration response for DC-8 takeoff.




Figure 14.- North window vibration response for B-707 takeoff.




Figure 15. North window vibration response for B-747 takeoff.




Figure 16.- North window vibration response for B-727 takeoff.

# RESPONSE SIGNATURE FOR-CTOL COMPOSITE




Figure 17.- North window vibration composite response for conventional aircraft takeoffs.




Figure 18.- North window vibration response ratio for Concorde and other aircraft during takeoff.